

APPENDIX F

OPERATIONS CHECKLIST

This appendix consists of an operations checklist of procedures (Table F-1) to be followed before, during, and after operation of the MK 19.

WEAPON PART	BEFORE	DURING	AFTER
1. Bore.	Ensure it is clear and clean.		Clean and oil lightly.
2. Moving parts.	Oil lightly and test for worn or broken parts. They should function without excessive friction.	Lubricate working parts. Observe the functioning of the gun to anticipate failures.	Inspect, clean, and oil lightly.
3. Ammunition.	a. Ensure correct type is used. b. Ensure it is clean and dent free. c. Ensure all ogives are tight. d. Have an adequate supply on hand.	Keep correctly aligned in the feedtray; check resupply; protect from sun, moisture, and dirt. Watch for link stoppage.	Clean, store carefully, and replenish supply.
4. Top cover.	Inspect for dents or damage.	Keep closed and locked down.	Lube properly after cleaning.
5. Line of fire.	Ensure line of fire is clear of all obstructions.	Cease fire if any obstruction appears in the line of fire.	

Table F-1. Operations checklist.